

Wilksch Airmolive Ltd

SERVICE BULLETIN WA-SB-004

SUBJECT:	Fuel Pump braided low pressure hoses –
	Lift Pump to Filter & Filter to Fuel Rail

- **DESCRIPTION:** Small amounts of fuel seeping from hoses
- **APPLICABILITY:** All serial numbers

COMPLIANCE: To be carried out prior to or at next 50 hour check

This Bulletin requires replacement of Lift Pump to Filter & Filter to Fuel Rail hoses with new items. P/Nos: 001957 & 001958. Also Washers P/No 001741, new items will be required. To achieve this, proceed as follows: -


Tools needed

17mm spanner, 10mm spanner, flat screwdriver and 11/16 spanner.

General.

certain that no dirt enters the pipes or fittings.

1) Support fuel filter with hand and undo fuel line with 17 mm spanner at the filter end.





2) Remove retaining clip from the lift pump end using a screwdriver and fingers. CAUTION: Do not let this clip spring off. Gently twist and pull the fuel line out of the lift pump.



Tel: 0870 170 9670 Fax: 0870 170 9678 Web: www.wilksch.com



Wilksch Airmolive

3) Unfasten the banjo bolt behind the fuel inlet.





4) Support the fuel filter with your hand and undo the banjo bolt, but only enough to free the hose.





5) Unfasten the fuel filter retaining nuts with a 10mm spanner.

6) Remove the fuel pressure hose



Tel: 0870 170 9670 Fax: 0870 170 9678 Web: www.wilksch.com



Wilksch Airmotive Ltd

Service Bulletin – WA-SB-004

7) Remove the fuel filter from the studs





8) Unfasten banjo bolt from filter

- Fit new washers P/N 001741 to banjo bolt either side of fuel line banjo – P/N: 001958



 Fit to fuel filter (pressure outlet end).
Do banjo up to touch but do not torque.

<u>Effective Date: 1 February 2009</u> Unit SE3, Gloucestershire Airport, Staverton. Gloucestershire. GL51 6SP. England



Wilksch Airmolive Ltd

Service Bulletin – WA-SB-004



11) Re-fit fuel pressure hose.

12) Re-fit fuel filter to studs and torque nuts to 12 NM

 Re-fit banjo bolt and washers to fuel line and fit to fuel pump body.
Support outer side of hose whilst torque of 25-30NM is applied, to prevent hose from spinning.

14) Now torque the fuel filter banjo to 25-30NM whilst also supporting the fuel line. Avoid fuel line from touching the fuel filter plate.







Tel: 0870 170 9670 Fax: 0870 170 9678 Web: www.wilksch.com



Wilksch Airmotive Ltd

Service Bulletin – WA-SB-004

 Fit banjo bolt and washers to hose P/N 001957 and re-fit to filter, hand tight.



16) Push and twist hose end into lift pump until fully seated. Re-fit retaining clip and torque filter end, 25-30 NM.



17) Remove fuel return fitting and discard washer. Fit new washer and torque to 25-30 NM.



Hoses removed need to be returned to Wilksch Airmotive Ltd., at the address below.

Failure to comply with any recommendations/limitations published by Wilksch Airmotive will invalidate your warranty.

<u>Effective Date: 1 February 2009</u> Unit SE3, Gloucestershire Airport, Staverton. Gloucestershire. GL51 6SP. England